


GSE 2022 Price List

<u>Line Item</u>	<u>Nomenclature</u>	<u>Part Number</u>	<u>Lead Time (Weeks)</u>	<u>Price (EA)</u>
	<u>Tool Kit, Tube Fitting</u>	<u>DLTFRPSKT3009</u>	<u>20</u>	<u>\$226,123</u>
	<u>Universal Blackhawk Access Stand Set</u>	<u>TA4226</u>	<u>18</u>	<u>\$139,999</u>
	<u>APU TEST SET, SIMULATOR, TEMP/SPEED</u>	<u>H296B-60</u>	<u>42</u>	<u>\$107,559</u>
	<u>IVHMS SUPPORT KIT</u>	<u>70700-25001-041</u>	<u>62</u>	<u>\$105,749</u>
	<u>Nitrogen Servicing Unit</u>	<u>1317AS100-1</u>	<u>4</u>	<u>\$103,593</u>
	<u>SWAGE TOOL KIT, HAND RYNGLOK</u>	<u>RCSK8-02-001</u>	<u>3</u>	<u>\$77,973</u>
	<u>Ground Power Unit (Diesel)</u>	<u>ACE4490STT3 -> 11-2820-0000</u>	<u>2</u>	<u>\$76,146</u>
	<u>Video Scope</u>	<u>MVIQAS4020-CO</u>	<u>10</u>	<u>\$75,593</u>
	<u>APU Adapter</u>	<u>70700-20423-041</u>	<u>48</u>	<u>\$74,729</u>
	<u>Buddy Start System</u>	<u>70073-30001-011</u>	<u>30</u>	<u>\$74,228</u>
	<u>Bearing Staking Tool Set</u>	<u>70700-77353-041</u>	<u>40</u>	<u>\$61,600</u>
	<u>Test Set, Multifunction (AN/USM-708)</u>	<u>90000108 (AN/USM-708)</u>	<u>18</u>	<u>\$57,260</u>
	<u>Blackhawk Phase Maintenance Tool Kit</u>	<u>PTMC-KIT</u>	<u>24</u>	<u>\$56,389</u>
	<u>REMOVAL SET, MAIN ROTOR HEAD</u>	<u>70700-77363-041</u>	<u>2</u>	<u>\$52,765</u>
	<u>Test Set, JT-147A Magnetometer Calibration</u>	<u>570-8552-01</u>	<u>62</u>	<u>\$47,600</u>
	<u>Tail Rotor Spring Capsule Holding Clamp</u>	<u>70700-77316-041</u>	<u>18</u>	<u>\$44,660</u>
	<u>Main Landing Gear Bearing Installer/Remover</u>	<u>70700-77533-043</u>	<u>40</u>	<u>\$36,207</u>
	<u>Bushing Installation and Removal Kit</u>	<u>65700-20002-041</u>	<u>36</u>	<u>\$31,500</u>
	<u>Tail Pylon Lifting Sling Assy</u>	<u>70700-77520-041</u>	<u>32</u>	<u>\$30,030</u>
	<u>Composite Repair Kit</u>	<u>70-700-CRK-041</u>	<u>16</u>	<u>\$27,790</u>
	<u>Battery Charger/Analyzer</u>	<u>RF80-M</u>	<u>13</u>	<u>\$27,583</u>
	<u>ADAPTER TRANSPORTATION (MAC)</u>	<u>21C7082G02</u>	<u>12</u>	<u>\$26,751</u>
	<u>Blind Rivet Set</u>	<u>353-51</u>	<u>4</u>	<u>\$22,819</u>
	<u>MULTIMODE EDDY CURRENT/BOND TESTER</u>	<u>MIZ-21B</u>	<u>4</u>	<u>\$21,388</u>



ISO 9001:2015 & ASP120B

<u>Test Set, Comms</u>	<u>IFR4000OPTI</u>	<u>4</u>	<u>\$20,559</u>
<u>Rail Trailer</u>	<u>4800-000-00</u>	<u>35</u>	<u>\$20,542</u>
<u>Trim Tab Adjust Tool Set</u>	<u>92700-10313-045</u>	<u>10</u>	<u>\$19,844</u>
<u>Blade Clamp</u>	<u>1006845</u>	<u>28</u>	<u>\$19,816</u>
<u>INSTALLER ASSY,</u>	<u>70700-77312-042</u>	<u>20</u>	<u>\$18,326</u>
<u>Puller, Pitch Beam,</u>	<u>65700-10048-041</u>	<u>40</u>	<u>\$17,987</u>
<u>Main and Tail Rotor Blade Storage</u>	<u>70700-20426-041</u>	<u>32</u>	<u>\$16,968</u>
<u>Main Rotor Blade Solid Pin Removal Tool</u>	<u>70700-25450-041</u>	<u>22</u>	<u>\$16,786</u>
<u>Mobile Fuel Tank Ventilating System</u>	<u>MAV-1</u>	<u>18</u>	<u>\$16,533</u>
<u>TGB Output Seal Installer</u>	<u>70700-77311-041</u>	<u>14</u>	<u>\$16,279</u>
<u>Multi-Stage Jack, Tripod, 12 Ton</u>	<u>CJ69J1270</u>	<u>26</u>	<u>\$16,110</u>
<u>Blackhawk Wiring Connector Repair Set</u>	<u>DMC787</u>	<u>12</u>	<u>\$15,329</u>
<u>Seal Remover</u>	<u>70700-77319-041</u>	<u>17</u>	<u>\$14,748</u>
<u>Tire Bead Beaker</u>	<u>5372-010</u>	<u>17</u>	<u>\$14,219</u>
<u>Tool Kit, General Aviation Master Tool Kit</u>	<u>GAMTK</u>	<u>30</u>	<u>\$13,796</u>
<u>Torque Wrench Kit</u>	<u>S-70 Torque Kit</u>	<u>28</u>	<u>\$13,790</u>
<u>Deluxe Sheet Metal Tool Kit</u>	<u>TP176DLX-4</u>	<u>14</u>	<u>\$12,459</u>
<u>Seal Puller AY</u>	<u>65720-10049-041</u>	<u>18</u>	<u>\$12,089</u>
<u>VESPEL SPLINE ADAPTER WITHDRAWAL TOOL</u>	<u>1106769-4</u>	<u>28</u>	<u>\$11,673</u>
<u>INSTALLER, TAIL</u>	<u>70700-77310-041</u>	<u>14</u>	<u>\$11,550</u>
<u>Sling Assembly, Hoist T-700 Engine</u>	<u>21C7081G02</u>	<u>14</u>	<u>\$11,052</u>
<u>Main Rotor Damper Bearing Installer/Remover</u>	<u>70700-77306-043</u>	<u>16</u>	<u>\$10,920</u>
<u>Grille, Inlet FOD, T-700</u>	<u>70700-20222-044</u>	<u>2</u>	<u>\$10,745</u>
<u>Rigging Kit</u>	<u>70700-20389-043 -></u> <u>FCRK-60-AA</u>	<u>8</u>	<u>\$10,710</u>
<u>TRB BOOT EXP TOOL</u>	<u>96700-15001-041</u>	<u>26</u>	<u>\$10,549</u>
<u>Maintenance Stand, B-4</u>	<u>51E24854 <- (outdated) -</u> <u>54J6345</u>	<u>36</u>	<u>\$10,150</u>
<u>Maintenance Stand, B-1</u>	<u>47R16420</u>	<u>36</u>	<u>\$10,080</u>
<u>Footlocker, Avum Toolkit</u>	<u>PEOAVN-B90</u>	<u>30</u>	<u>\$10,073</u>
<u>Rotor Head Adapter</u>	<u>70700-20421-041</u>	<u>32</u>	<u>\$9,982</u>
<u>Nitrogen Servicing Unit, Portable</u>	<u>1428AS100-1</u>	<u>12</u>	<u>\$9,933</u>
<u>Oil Cooler Adapter</u>	<u>70700-20425-041</u>	<u>32</u>	<u>\$9,660</u>
<u>Jack, 5 Ton</u>	<u>53D22020</u>	<u>36</u>	<u>\$9,576</u>
<u>Main Gear Box Adapter</u>	<u>70700-20420-041</u>	<u>32</u>	<u>\$9,072</u>
<u>VESPEL SPLINE ADAPTER INSTALLATION TOOL</u>	<u>1106841-1</u>	<u>28</u>	<u>\$8,793</u>
<u>Tire Cage</u>	<u>SK2000TC-6</u>	<u>10</u>	<u>\$8,568</u>
<u>TESTER,CIRCUIT</u>	<u>21C7085G01</u>	<u>12</u>	<u>\$8,040</u>



<u>Swashplate Bearing Remover/Installer</u>	<u>3218AS161-1</u>	<u>36</u>	<u>\$7,778</u>
<u>Strut Assembly, Stabilator Fold</u>	<u>70700-77446-041</u>	<u>20</u>	<u>\$6,930</u>
<u>Tire Bead Beaker</u>	<u>14-6801-0120</u>	<u>9</u>	<u>\$6,906</u>
<u>Puller Set, Master Interchangeable</u>	<u>CJ2000SB</u>	<u>2</u>	<u>\$6,762</u>
<u>Pilot Static Accessories Kit</u>	<u>ADA60A-835</u>	<u>11</u>	<u>\$6,529</u>
<u>Tester Kit, 1553 Data Bus</u>	<u>NH17149 -> DBT100A</u>	<u>14</u>	<u>\$6,083</u>
<u>Test Set, Underwater Locating Beacon</u>	<u>TS-200</u>	<u>2</u>	<u>\$5,931</u>
<u>STAKING TOOL</u>	<u>RST2459</u>	<u>2</u>	<u>\$5,670</u>
<u>AIRFRAME TOOL KIT</u>	<u>PEOAVN-B02</u>	<u>30</u>	<u>\$5,628</u>
<u>Meter Vector Impedance</u>	<u>TE3000</u>	<u>4</u>	<u>\$5,530</u>
<u>Tail Rotor Pilot Bearing Installer</u>	<u>70700-77397-041</u>	<u>36</u>	<u>\$5,460</u>
<u>Hoisting Sling</u>	<u>70700-77403-041</u>	<u>18</u>	<u>\$5,304</u>
<u>Installation Tool, Tail Flange Support,</u>	<u>70700-20688-041/1680-</u>	<u>2</u>	<u>\$4,795</u>
	<u>01-105-1496</u>		
<u>Swashplate Expandable Pin Torque Adapter</u>	<u>70700-77395-101</u>	<u>12</u>	<u>\$4,774</u>
<u>AIRCRAFT WEIGHING SYSTEM</u>	<u>M2000-3-10KP -- ALT--</u>	<u>2</u>	<u>\$4,718</u>
	<u>JX701</u>		
<u>STAKING TOOL</u>	<u>RST2154</u>	<u>18</u>	<u>\$4,690</u>
<u>Portable Microohm and Bond Meter Kit</u>	<u>R1L-BR1 replacement -></u>	<u>3</u>	<u>\$4,561</u>
	<u>R1L-BIR1</u>		
<u>Tool Kit, Stud Removal</u>	<u>RZA11197</u>	<u>2</u>	<u>\$4,550</u>
<u>Time Domain Reflector Cable Tester</u>	<u>CFL535G</u>	<u>2</u>	<u>\$4,035</u>
<u>Expandable Pin Wrench</u>	<u>70700-20210-102</u>	<u>12</u>	<u>\$3,850</u>
<u>INSERT KIT</u>	<u>K4-314-314L</u>	<u>19</u>	<u>\$3,710</u>
<u>Power Plant Tool Kit</u>	<u>KIT PEOAVN-B07-VTB</u>	<u>30</u>	<u>\$3,709</u>
<u>Fly Cutter</u>	<u>RST1013</u>	<u>5</u>	<u>\$3,703</u>
<u>Maintenance Folding Platform</u>	<u>1730-EG-012</u>	<u>11</u>	<u>\$3,687</u>
<u>Spindle Bender Kit</u>	<u>1006748</u>	<u>28</u>	<u>\$3,640</u>
<u>Test Set, ELT</u>	<u>8701</u>	<u>5</u>	<u>\$3,563</u>
<u>Electrical Repairer Tool Kit</u>	<u>KIT PEOAVN-B06-VTB</u>	<u>30</u>	<u>\$3,503</u>
<u>Kit, Screw THD</u>	<u>K4-192-192L</u>	<u>21</u>	<u>\$3,500</u>
<u>INSERT KIT</u>	<u>K4-258-258L</u>	<u>27</u>	<u>\$3,465</u>
<u>General Mechanics Tool Kit</u>	<u>KIT PEOAVN-B01-VTB</u>	<u>30</u>	<u>\$3,408</u>
<u>Plug, Drain Hose Assembly</u>	<u>D730L/1560-00-018-6430</u>	<u>20</u>	<u>\$3,401</u>
<u>POWERTRAIN TOOL KIT</u>	<u>PEOAVN-B13</u>	<u>30</u>	<u>\$3,372</u>
<u>Hydraulic Repairer Tool Kit</u>	<u>KIT PEOAVN-A03-VTB</u>	<u>30</u>	<u>\$3,128</u>
<u>Z-Bar Wrench (LOCAL MAKE)</u>	<u>GB-L26A-553 -> 1420-</u>	<u>30</u>	<u>\$3,080</u>
	<u>BH-008</u>		
<u>Bifilar Bolt Torque Reactor</u>	<u>70700-77398-041</u>	<u>24</u>	<u>\$3,024</u>
<u>TOOL KIT, SCREW THREAD INSERT</u>	<u>K4-162-162L</u>	<u>2</u>	<u>\$2,876</u>



<u>Set Dresser, Leading Edge, Stage 1 Blade-Disk</u>	<u>21C7478G01</u>	<u>4</u>	<u>\$2,793</u>
<u>Inspection Penetrant Kit</u>	<u>626776</u>	<u>8</u>	<u>\$2,646</u>
<u>ANTENA TESTER</u>	<u>AT-500</u>	<u>8</u>	<u>\$2,479</u>
<u>Technical Inspector Tool Kit</u>	<u>KIT PEOAVN-A09-GSA</u>	<u>30</u>	<u>\$2,476</u>
<u>Aircraft Hydraulic Fluid Filler/Bleeder</u>	<u>AF5</u>	<u>16</u>	<u>\$2,241</u>
<u>Walk Around ICS Cable</u>	<u>70600-85828-106</u>	<u>2</u>	<u>\$2,233</u>
<u>FUNCTION GENERATOR</u>	<u>33210A</u>	<u>3</u>	<u>\$2,072</u>
<u>Cover, Inlet, Engine</u>	<u>21C7396P01</u>	<u>12</u>	<u>\$2,043</u>
<u>HMU Torque Check Tool</u>	<u>18C2268-1/5120-01-500-9990</u>	<u>2</u>	<u>\$2,030</u>
<u>ADAPTER PLUG</u>	<u>21C7086P01</u>	<u>12</u>	<u>\$1,960</u>
<u>Pylon Tq Adaptors</u>	<u>1006772</u>	<u>28</u>	<u>\$1,960</u>
<u>TOOL KIT, FSTNR, HI-LOK</u>	<u>HLK10</u>	<u>2</u>	<u>\$1,960</u>
<u>Tail Lockout Blocks</u>	<u>70700-20463-041</u>	<u>8</u>	<u>\$1,879</u>
<u>Rotor Brake Wrench</u>	<u>70700-77117-041</u>	<u>14</u>	<u>\$1,750</u>
<u>TOOL KIT, FSTNR, HI-LOK</u>	<u>HLK14</u>	<u>2</u>	<u>\$1,750</u>
<u>PULLER, CARBON SEAL, AXIS-G</u>	<u>21C7239G02</u>	<u>8</u>	<u>\$1,723</u>
<u>Socket</u>	<u>18C2268-2</u>	<u>2</u>	<u>\$1,715</u>
<u>Tail Drive Shaft Alignment Fixture</u>	<u>70700-77333-048</u>	<u>24</u>	<u>\$1,694</u>
<u>PROTRACTOR FIXTURE (STABILATOR)</u>	<u>A3012559</u>	<u>11</u>	<u>\$1,674</u>
<u>Blind Rivet Set</u>	<u>D-100-MIL-2</u>	<u>6</u>	<u>\$1,540</u>
<u>Beacon Battery Replacement Tools</u>	<u>810-2007/KVS</u>	<u>2</u>	<u>\$1,506</u>
<u>POSITIONER ASSY, CHIP DETECTOR</u>	<u>70700-20403-045</u>	<u>2</u>	<u>\$1,393</u>
<u>Fixture, Igniter Removal</u>	<u>21C7765G01</u>	<u>6</u>	<u>\$1,365</u>
<u>Hot Section Wash Kit</u>	<u>1226-410KT</u>	<u>5</u>	<u>\$1,281</u>
<u>DRIVE TOOL (BIFILAR)</u>	<u>REA048D</u>	<u>30</u>	<u>\$1,225</u>
<u>PULLER, SEAL MATTING RING</u>	<u>21C7702G01</u>	<u>4</u>	<u>\$1,187</u>
<u>Tire Inflation Safety Kit</u>	<u>M85352/1</u>	<u>9</u>	<u>\$1,183</u>
<u>Caliper, Master Vernier</u>	<u>123Z-6</u>	<u>2</u>	<u>\$1,133</u>
<u>TENSIOMENTER</u>	<u>T5-2002-104-00</u>	<u>4</u>	<u>\$1,132</u>
<u>Dummy Load</u>	<u>500-WT-FN</u>	<u>12</u>	<u>\$1,095</u>
<u>Tire Bead Beaker</u>	<u>Z-1063-14</u>	<u>13</u>	<u>\$941</u>
<u>Wattmeter</u>	<u>43P</u>	<u>6</u>	<u>\$927</u>
<u>Tap and Die Set</u>	<u>TD9902</u>	<u>4</u>	<u>\$926</u>
<u>Micrometer Set</u>	<u>MIC103B (discontinued) - > MIC0-3E</u>	<u>2</u>	<u>\$905</u>
<u>H-60 Tq Adaptors</u>	<u>1006767</u>	<u>28</u>	<u>\$883</u>
<u>RF TERMALINE DUMMY LOAD</u>	<u>8135</u>	<u>6</u>	<u>\$868</u>
<u>Tire Bead Beaker</u>	<u>Z-1063-08</u>	<u>7</u>	<u>\$867</u>



ISC 0001.2015 & ASP120B

<u>Plug, Leakproof, T-700 Engine,</u>	<u>70700-20114-109</u>	<u>6</u>	<u>\$839</u>
<u>Star Plate Kit</u>	<u>1006779</u>	<u>28</u>	<u>\$837</u>
<u>Spindle Tq Adaptor</u>	<u>900158</u>	<u>28</u>	<u>\$819</u>
<u>Drain Line, TGB/IGB</u>	<u>H538A-3</u>	<u>22</u>	<u>\$770</u>
<u>MLG Tq Adaptor</u>	<u>1006776</u>	<u>28</u>	<u>\$770</u>
<u>Spanner Wrench</u>	<u>AN8515-1</u>	<u>2</u>	<u>\$723</u>
<u>Rugged Digital Multimeter</u>	<u>FLUKE 27II</u>	<u>2</u>	<u>\$700</u>
<u>Engine Cover, Multi-Purpose</u>	<u>21C7088P01</u>	<u>2</u>	<u>\$694</u>
<u>Tail Drive Flange Wrench</u>	<u>70700-20687-102</u>	<u>2</u>	<u>\$630</u>
<u>Depth Gage, Dial Indicating</u>	<u>643JZ</u>	<u>2</u>	<u>\$603</u>
<u>Hand Tool for Plastic and Metal tie straps</u>	<u>MS90387-2</u>	<u>2</u>	<u>\$592</u>
<u>Thermometer, Dual Input Digital</u>	<u>FLUKE-52-2</u>	<u>3</u>	<u>\$591</u>
<u>Pump, Inflating, Manuel</u>	<u>700PMP</u>	<u>2</u>	<u>\$580</u>
<u>Test Cable, Coaxial, 50 Ohm</u>	<u>TC-MNMN-1.5</u>	<u>4</u>	<u>\$511</u>
<u>Digital Protractor</u>	<u>KS5549</u>	<u>2</u>	<u>\$442</u>
<u>Ground Strap Circuit Tester</u>	<u>WT25</u>	<u>4</u>	<u>\$409</u>
<u>SPRING SCALE (40 LB)</u>	<u>719-040M</u>	<u>3</u>	<u>\$376</u>
<u>Spring Scale</u>	<u>719-010M</u>	<u>3</u>	<u>\$376</u>
<u>Spring Scale</u>	<u>719-005M</u>	<u>3</u>	<u>\$376</u>
<u>Bushing Driver Set</u>	<u>A57Q (discontinued) -> A157C</u>	<u>2</u>	<u>\$332</u>
<u>Puller Set, Blind Hole Bearing</u>	<u>CG40CB (discontinued) - > SIRST9006</u>	<u>2</u>	<u>\$310</u>
<u>Indicator, Dial</u>	<u>196A1Z</u>	<u>16</u>	<u>\$309</u>
<u>Probe, Straight, Shielded Surface, 50- 500khz</u>	<u>MP-60</u>	<u>2</u>	<u>\$161</u>
<u>Telescoping Gage Set</u>	<u>MTEE6</u>	<u>2</u>	<u>\$159</u>
<u>Wattmeter Element</u>	<u>25D</u>	<u>6</u>	<u>\$147</u>
<u>WATTMETER ELEMENT</u>	<u>25C</u>	<u>8</u>	<u>\$147</u>
<u>WATTMETER ELEMENT</u>	<u>25B</u>	<u>8</u>	<u>\$147</u>
<u>WATTMETER ELEMENT</u>	<u>250D</u>	<u>8</u>	<u>\$147</u>
<u>Scale, Digital</u>	<u>CS-5000 (discontinued) -> H-3677</u>	<u>2</u>	<u>\$97</u>
<u>Stap Wrench, 12"</u>	<u>40221 (discontinued) -> 5PV88</u>	<u>2</u>	<u>\$84</u>
<u>Crowfoot, 2 1/4"</u>	<u>FC72A</u>	<u>2</u>	<u>\$74</u>
<u>Tire Pressure Gauge</u>	<u>6637A24</u>	<u>2</u>	<u>\$70</u>
<u>Grease Gun</u>	<u>GA473A</u>	<u>2</u>	<u>\$51</u>
<u>Kwik Tite Wrench, 7/8</u>	<u>195-F 14</u>	<u>5</u>	<u>\$48</u>
<u>Feeler Gauge Set</u>	<u>FBL325A</u>	<u>2</u>	<u>\$37</u>
<u>Socket Drive</u>	<u>TTX20E</u>	<u>2</u>	<u>\$36</u>
<u>Cargo Strap, 5,000 lbs.</u>	<u>CGU-1/B</u>	<u>5</u>	<u>\$36</u>



ISO 9001:2015 & AS9100B

	<u>Strap Wrench</u>	<u>YA826A (discontinued) -></u> <u>LIL28500</u>	<u>2</u>	<u>\$35</u>
	<u>Small Arms Cleaning Kit</u>	<u>5564102</u>	<u>2</u>	<u>\$33</u>
	<u>Magnifying Glass, 10X, Illuminated</u>	<u>81-34-34</u>	<u>2</u>	<u>\$31</u>
	<u>PLUMB BOB</u>	<u>5720-10</u>	<u>2</u>	<u>\$14</u>
	<u>Feeler Ga Ge, Plastic</u>	<u>78905</u>	<u>2</u>	<u>\$2</u>